


Eastern Industries Shop Floor Education

Decimals and Measurement

Mathmatical Expression


(what you learned in school)



Industrial Expression

(what you need to know on the shop floor)

These are called tenths because they are **1/10** of a thousandth. (there are 10 tenths in one thousandth)



Common examples

.005	Five thousandths
.105	One hundred five thousandths
.2114	Two hundred eleven thousandths and four tenths
.10805	One hundred eight thousandths and fifty milionths